# U.S. ENVIRONMENTAL PROTECTION AGENCY. POLLUTION REPORT

DATE: December 13, 1990

Region II Air and Hazardous Substances Staff EPA Caribbean Field Office Santurce Puerto Rico 00910 and Response and Prevention Branch Edison, New Jersey 08837

TO: R. Caspe, EPA R. Salkie, EPA B. Sprague, EPA P. Gelabert, EPA W. Mugdan, EPA G. Pavlou, EPA J. Carter, EPA , ERD Washington (E - Mail) .USCG 7th District (mep) NRC ATSDR . J. Anderson, HHS A. Zack, USGS Caribbean RRT S. Rohena, PREQB F. Claudio, PREQB J. Segarra, CD E. Ortiz, LEPC

POLREP NO.:

Eight (8). 7 /

INCIDENT/SITE NO.: G - 7

POLLUTANT: Volatile and aromatic organics, heavy metals,

oil.

CLASSIFICATION:

Major

SOURCE: Muratti Environmental site.

LOCATION:

State Road 385, Km. 3.5, Tallaboa Ward,

Penuelas, P.R.

Unknown.

AFFECTED MEDIUM:

Air, soil, ground and surface water:

#### SITUATION: 1.

Same as previous Pol Rep. .

## 2. ACTION TAKEN:

### November 17, 1990

- A. Drum staging area prepared. Staging of overpacks initiated.
- B. Results of the geophysical survey performed on the southern area of the site revealed no conductivity or magnetic anomalies.
- C. EPA instructed ERCS that the level of protection can be lowered to Level D for the preparation of the staging area.

# November 19, 1990

- A. Lab jars segregation was completed. The jars were taken to the area designated for the crushing activities.
- B. All overpack drums were placed on the staging area.
- C. Two of the three aboveground tanks were sampled. One was determined to be empty.
- D. Overpack sampling continued.

# November 20, 1990

- A. Lab jars crushing and overpacking activities were completed. The crushing device broke several times, therefore, the OSC instructed ERCS to place the jars in overpack drums and crush them.
- B. Ambient air monitoring was conducted during the crushing activities with an organic vapor analyzer (OVA), a photoionization detector (HNU) with a 10.2 ev lamp, and a combustible gas indicator (CGI). The readings obtained were:

#### OVA:

0-3 ppm, 25 ft downwind from the crushing area. 12 ppm, inside overpack drum with crushed jars.

#### HNU:

0 ppm, 25 ft downwind from the crushing area. 1-25 ppm, probe inmediately above the drum. 40 ppm, probe directly into the drum.

# CGI:

No readings above background (O LEL, 21% oxygen).

C. During the segregation of lab jars, it was determined that most were production samples from a nearby refinery, therefore, 20 random samples of the jars were taken and composited for analyses.

D. Overpack sampling continued.

# November 21, 1990: ....

- A. Overpack sampling activities completed.
- B. Some oil contaminated soil was removed and placed in an overpack drum.
- Overpack staging area was covered with plastic sheeting.
- \*\* All equpment and machinery was decontaminated.

E. ERCS and EPA demobilized.

# MEASURES WHICH COULD AVOID RELEASES OF SIMILAR NATURE:

Unknown at this time.

n. 1. ...

# 4. FUTURE PLANS AND RECOMMENDATIONS:

- A. EPA will transport and finally dispose of the material contained in the overpack drums.
- C. EPA will continue the Enforcement Action against ROHO

  Investment Corporation and Mr. Muratti.

5.	FINAN	CIAL ACCOUNTING		
- 4	A.	Total Project Ceiling Authorized	\$	237,000.00
	В	Total Funds Authorized for Mitigation Contracts	\$	154,000.00
• ,	C.	Expenditures for Mitigation Contracts  1. Amount Obligated - DCN # KE0003 KE0006	\$	154,000.00
<i>i</i> ,		2. Estimated Expenditures (as of 11/21/90)	\$	139,000.00
		3. Balance Remaining	\$	15,000.00
	D.	Unobligated Balance Remaining	\$	0.00
	E.	Estimated Total Expenditures to Date for Mitigation Contracts	\$	139,000.00
	F.	Other Extramural Costs  1. TAT Salary/Travel Expenses		*
			\$	431,75% 81
	· · .	2. REAC	\$	10,000.00
	G.	Intramural Removal Costs		
				11,000.00
	H.	Total Expenditures	\$	191,751.61
		Percentage of \$2 million		9.6%
•	I.	Percentage of Total Project Ceiling	2 <sup>6</sup> 771	80.9%

FURTHER PO	DLREPS FORTHCOMING: FINAL POLREP:
SUBMITTED	
	Angel Rodriguez, OSC Environmental Protection Agency
9	Response & Prevention Branch Edison, New Jersey